ECS Configuration C	hange Request				Page 1 of	}	Page(	s)
1. Originator	2. Log Date:	3. CCR #:		4. Rev:	5. Tel:		6. Rm #:	7. Org.
Jim Mather	3/31/99	99-0	269	_	0435		2107a	sed
8. Title of Change: Planning							<u>.                                    </u>	
o. Hao or orlange. Hamming	and adding conton up;	gidde Emergen	٠,					
9. Originator Signature/Date  3/3/49  10. Class 11. Type: 12. Need Date: 4/1/99 CCR						1/99		
13. Office Manager Signature/Date 14. Category of Change			hange:	15. Priority: (If "Emergency"				
Similator for Ribollinger - 3/3/49 Update Base			aseline	fill in Block 28). Emergency				
6. Documentation/Drawings Impacted: 17. Schedule 18. Cl(s) Affected:bear, buterfly, l0pls(							ly, l0pls01,	
920-TDL-001   Impact:   I0pls02 and I0sps01   yes								
19. Release Affected:		20. Date due	o Custome	er: 21.	Impl. Date:	;	22. Estimate	ed Cost:
na		4/1/99		4/1.	/99	[	Small	
23. Source Reference:	□NCR (attach) □A	ction Item	Tech Ref.	GSFC	∷ ⊠Other:			
Direction from Robert Plante - unable to do end to end testing at LaRC								
24. Description of Change: (use additional Sheets if necessary)								
Ship bear and butterfly to LaRC to replace l0pls01 and l0sps03. Use the SUN Ultra2 removed from l0pls01 and replace l0pls02.								
Return to EDF the two removed machines (ein 1907 ein 1415) The multi-packs remain with the new machines.								
25 Proposed Solution: /ui	en additional chapte if	necessary)		<del></del>				
25. Proposed Solution: (use additional sheets if necessary)  The current planning and quoing sorver are rupping at 08% consoity and cannot support and to end testing. This solution brings								
The current planning and queing server are running at 98% capacity and cannot support end to end testing. This solution brings those servers in line with similar servers at EDC and GSFC.								
tilose servers in line with sim	ilai servers at CDC and	1 031 0.						
26. Alternate Solution: (use additional sheets if necessary)								
none								
27. Consequences if Change(s) are not approved: (use additional sheets if necessary)								
end to end testing can not happen,								
28. Justification for Emerg	ency (If Block 15 is "E	Emergency"):						
end to end testing is at a stand still								
29. Site(s) Affected: ⊠E	DF Mini-DAAC	VATC [EDC	GS	FC 🛛 La	RC   NSID	C	SMC □AK	□JPL
Z5. Site(s) Affected. ⊠E				. 6 2			,	
30. Board Comments:					31. V	Nork A	ssigned To:	
					1	,	•	
						AR	0	
$\sim$					4	, / ' '	<u>,                                    </u>	
/)								
32. EDF/REL2 CCB Chair (	Sign/Date): /	33. Dispositi	07: Ann	roved	34.	(TBD	<u> </u>	<del></del>
JZ. EDFIRELZ WGB CHair (	7 3 / /	A/C		proved	<u> </u>	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	•	
1 XII In. 1	1 2/31/99			-	1			
35. M&B CCB Chair (Sign/	Data):	Fwd/ECS			27	CM M	nager's Clos	Bille.
35. Map CCB Chair (Sign/	Date): / /	36. Dispositi			37.	OIM MIS	mayer a Citi	Jui E.
		A/C	Disapp	noved				
/ /	i	<i>-</i>	E 1,000	CDIC	1			
38. EÇS CCB Chair (Sign/I	lato):	Fwd/ECS 39. Disposit			40	CCB	Closed Date:	,

CM01 March 8, 1999

Disapproved

ECS/EDF/REL2 CCB